

Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd. Wood Village, OR 97060 (503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

| Vehicle Description | | | | | | | | |
|--|---------------------|----------------|--|--|--|--|--|--|
| 2007 Dodge Durango 4WD 4D SUV 4WD SXT 4.7L | | | | | | | | |
| VIN | 1D8HB38 | 3P07F565373 | | | | | | |
| Ext. Color | Silver | | | | | | | |
| Int. Color | Gray | Interior Cloth | | | | | | |
| Mileage | 23,097 Actual Miles | | | | | | | |
| Engine | 4.7L 8-Cylinder Gas | | | | | | | |
| Transmission | Automatio | C | | | | | | |



| | Auctio | on Data | | Declarations |
|-----------|---------------------------|----------------------|---------------|--|
| Sale Date | Mon - Feb 8 | - Open to the Public | Warranty | GSA Regular Terms |
| Run# | W044 | Inv # 5596 | Mileage | 23,097 Actual Miles |
| Consignor | signor GSA FLEET SERVICES | | Title | Clear Title |
| | | | Announcements | CNDTN UNKWN,PRTS MAYBE MSNG,RPRS MAYBE NEEDED |

Equipment

- 4 Wheel Drive
- Air Conditioning
- Trip Counter
- · Steel Wheels
- Towing Package
- Power Steering

- Automatic Transmission
- Electronic Traction Control
- Dual and Side Air Bags
- Tilt Steering Wheel
- Hard Top
- Power Brakes

- 8 Cylinder Gas
- Power Windows
- Cruise Control
- AM/FM CD
- Rear Wiper
- Electric Mirrors

- 8 Passenger
- Power Locks
- Anti Lock Brakes
- Keyless Entry
- · Rear Defog

| | Damage Descriptions (CR completed on 11/20/2015 by SKYLAR FICKLIN) | | | | | | | | | |
|-------|--|----------|------------------|--------------------|----------|----------|-----------------|-------------|---------------|-------|
| | # | Location | Damage Action | Severity | Parts \$ | Other \$ | Repair hours | Paint hours | Part hours | Total |
| Front | 1 | Hood | Chips | Multiple Instances | | | | | | |
| | | | | Front Subtotal | - | - | | | | |

2007 Dodge Durango 4WD 4D SUV 4WD SXT 4.7L

VIN: 1D8HB38P07F565373 **Inv#:** 5596

| | # | Location | Damage Action | Severity | Parts \$ | Other \$ | Repair hours | Paint hours | Part hours | Tota |
|----------|---|--------------------|--------------------|--------------------|----------|----------|-----------------|----------------|---------------|------|
| Interior | | 2004 | 7.00.0 | | | | | | | |
| | 2 | Left Front Seat | Worn | Multiple Instances | | | | | | - |
| | | | | Interior Subtotal | | | - | | | - |
| | | | | | | | - | - | - | - |
| Left | | | | | | | | | | |
| | 3 | Left Front Door | Scratched | Multiple Instances | | | | | | • |
| | 4 | Left Front Window | Inoperable | Other | | | | | | |
| | - | | 1 | | | | | | | |
| | | | | Left Subtotal | | | | | | - |
| | | | | | | | | | | - |
| Rear | | | | | | | | | | |
| | 5 | Rear Door | Scratched | Multiple Instances | | | | | | - |
| | | | | | | | | | | - |
| | | | | Rear Subtotal | - | | | | | - |
| D:ada4 | | | | | | | | | | - |
| Right | 6 | Right Front Fender | Dents W/ Paint Dmg | 4 To 5 Inches | | | | | | _ |
| | | g | | | | | | | | - |
| | 7 | Right Qtr Panel | Light Scratch | Multiple Instances | | | | | | - |
| | | D' L' D | 1:1:0 | AA III II I | | | | | | - |
| | 8 | Right Rear Door | Light Scratch | Multiple Instances | | | | | | - |
| | | | | Dimba Occident | | | | | | |
| | | | | Right Subtotal | _ | - | - - | - - | | - |
| | | | | | | | | | | |
| | | | | Total | - | - | | | | - |
| | | | | | | | | | | |

| Tires | | | | | |
|-------------|----------|------|-------------------|--|--|
| Region | Brand | Size | Tread Depth | | |
| Left Front | GOODYEAR | /- | Average (Average) | | |
| Left Rear | GOODYEAR | /- | Average (Average) | | |
| Right Front | GOODYEAR | /- | Average (Average) | | |
| Right Rear | GOODYEAR | /- | Average (Average) | | |
| Spare | FACTORY | /- | Average (Average) | | |

2007 Dodge Durango 4WD 4D SUV 4WD SXT 4.7L

VIN: 1D8HB38P07F565373 **Inv#:** 5596

Miscellaneous

Coolant level OK
Interior odor OK
Oil level OK
Transmission fluid level OK

Images

















